


# Rapid Drills Throw-Away Inserts

Dx4 捨棄式快速鑽頭



Model No.	Insert	d	D	L (Dx4)	Screw	Wrench
14WCMX	WCMX030208	32	14	56	M2.5x0.45	T8
16WCMX			16	64		
19WCMX			19	76		
20WCMX	WCMX040208		20	80		
21WCMX			21	84		
22WCMX			22	88		
23WCMX	WCMT050308		23	92	M3.0x0.5	T10
24WCMX			24	96		
25WCMX			25	100		
26WCMX	WCMT06T308		26	104	M3.5x0.6	T15
27WCMX			27	108		
28WCMX			28	112		
29WCMX	WCMT06T308	29	116	M3.5x0.6	T15	
34WCMX		34	136			
39WCMX		WCMT080412	39			156
41WCMX	41		164			
43WCMX	WCMT080412		43	172		
44WCMX		40	44	176		
47WCMX			47	188		
50WCMX	WCMT06T308		50	200	M3.5x0.6	T15
54WCMX		54	216			
59WCMX		59	236			

Unit: mm

# WCMX

# Accessories




- Insert must be ordered separately.
- 刀片為另購品



**P247**  
Torque wrench

# Modular Concentricity Test Gauge

三點組合模具



Model No.	FIG.	Taper Shank	A	B	C	Weight (kg)
BT30 A.T.C.	1	MAS403-BT	-	-	-	0.60
BT40 A.T.C.			-	-	-	1.30
BT50 A.T.C.			-	-	-	4.30
SK30 A.T.C.	1	SK-DIN69871A	-	-	-	0.60
SK40 A.T.C.			-	-	-	1.10
SK50 A.T.C.			-	-	-	3.40
CAT30 A.T.C.	1	CAT	-	-	-	0.60
CAT40 A.T.C.			-	-	-	1.10
CAT50 A.T.C.			-	-	-	3.40
HSK50A A.T.C.	2	HSK	50	25	25	1.10
HSK63A A.T.C.			63	32	30	1.70
HSK100A A.T.C.			100	50	40	4.70

Unit: mm

# A.T.C.




FIG.1



FIG.2

- Use for test the A.T.C. device of machine center.